

Summary of Asbestos Locations Hamilton Health Sciences, West Lincoln Memorial Hospital

Main Hospital - Front Wing (1948)

	Basement Level			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Throughout Building on Pipe Fittings: Locker Room, Inventory Storage, Inventory Room, Loading Area, Central Service Rooms, Surgery Tool Disinfecting Room, Offices #1 to #9, Board Room, Admin/Medical Affairs Office, Staff Washroom, PM. Office, Records Retention, Maintenance Shop, Boiler Room, Laundry Room, Linen Storage, Linen Sorting, Storage Rooms, Corridor, and Stairwells.	1500 Fittings	N/A	Chrysotile
Aircell	Throughout Building on Straight Sections of Pipe: Locker Room, Inventory Storage, Inventory Room, Loading Area, Central Service Rooms, Surgery Tool Disinfecting Room, Offices #1 to #9, Board Room, Admin/Medical Affairs Office, Staff Washroom, PM. Office, Records Retention, Maintenance Shop, Boiler Room, Laundry Room, Linen Storage, Linen Sorting, Storage Rooms, Corridor, and Stairwells.	2000 LF	N/A	Chrysotile
VFT – 12”x12” Dark Green with White Streaks	Basement Office #1	400 SF	0006A	VFT - Chrysotile Mastic – None Detected



VFT – 12"x12" Yellow with White Streaks	Basement Office #1	<1 SF	0007A and 0006A-C Phase b	VFT - Chrysotile Mastic – None Detected
VFT – 9"x9" Green with White Streaks	Basement Locker Room, Inventory Storage, and Washroom in Office #6	900 SF	0013A	VFT - Chrysotile Mastic – None Detected

	Ground Floor			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Throughout Building on Pipe Fittings: Stairwells.	N/A	N/A	Chrysotile
Aircell	Throughout Building on Straight Sections of Pipe: Stairwells.	N/A	N/A	Chrysotile
VFT – 12"x12" Dark Green with White Streaks	Ground Floor Wash Area	100 SF	0006A	VFT - Chrysotile Mastic – None Detected

	First Floor			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Throughout Building on Pipe Fittings: Corridor (Beneath Floor Hatches).	N/A	N/A	Chrysotile
Aircell	Throughout Building on Straight Sections of Pipe: Corridor (Beneath Floor Hatches).	N/A	N/A	Chrysotile
VSF - Orange Fleck	First Floor Staff Lounge and Washroom	400 SF	0043A	Chrysotile
VSF - Grey and White Squares	First Floor Medical Storage	100 SF	0046A	Chrysotile



VFT – 12”x12” Grey with Brown and White Streaks with White Streaks	First Floor Storage Closets	200 SF	0044A-C	VFT - Chrysotile Mastic – None Detected
Paper Heat Shields	First Floor Storage Closets	2 Heat Shields	0045A	Chrysotile

Main Hospital - Middle Wing (1960's)

	Basement Level			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Throughout Building on Pipe Fittings: Mechanical Room, Physio Department, Offices, Accounting Department, Conference Area, Washrooms, Waiting Room, File Storage, Mechanical Room, Medical File Storage, Electrical Room, Corridors, Vestibules, and Stairwells.	1500 Fittings	N/A	Chrysotile
Parging Cement on Cushion Tank	Basement Mechanical Room	30 SF	N/A	Chrysotile
VFT – 9”x9” Beige with Grey Streaks	File Storage Room, East Corridor, Waiting Room, Vestibule, Accounting Department, Main Corridor and Stairwells.	N/A	019A	VFT - Chrysotile Mastic – Chrysotile
VFT – 12”x12” Dark Green with White Streaks	Basement Main Corridor	200 SF	0006A	VFT - Chrysotile Mastic – None Detected
Transite Board (Above Ceiling)	Basement Medical Storage Room South End of the Main Corridor	400 SF 100 SF	N/A	Presumed ACM



Ground Floor				
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Throughout Building on Pipe Fittings: Washrooms, Cleaning Room, Dressing Room #1, Dark Room, Nurses Station, Waiting Room, Corridor.	N/A	N/A	Chrysotile
VSF - Brown with White Squares	Ground Floor Barrier-Free Shower	100 SF	0040A	Chrysotile
VFT – 9"x9" Beige with Grey Streaks	Main Corridor, Dressing Room #1 and #2, Radiology Suite, Patient Rooms, Linen Storage, Nurses Station, Office and Stairwells.	N/A	019A	VFT - Chrysotile Mastic – Chrysotile
VFT – 12"x12" Dark Green with White Streaks	Ground Floor Main Corridor	200 SF	0006A	VFT - Chrysotile Mastic – None Detected

First Floor				
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Throughout Building on Pipe Fittings: Operating Department, Janitors Closet, Washroom, Closets within Patient Rooms.	N/A	N/A	Chrysotile
VFT – 9"x9" Beige with Grey Streaks	Main Corridor, Patient Rooms, Offices, Accessible Areas in Operating Department, Intensive Care Unit, Waiting Room and Stairwells.	N/A	019A	VFT - Chrysotile Mastic – Chrysotile

Main Hospital - ER Wing (1970's)

Basement Level				
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Parging Cement	Basement Mechanical Room	200 Fittings	N/A	Chrysotile



VFT – 12"x12" Yellow with White Streaks	Basement Corridors	N/A	0007A	VFT - Chrysotile Mastic – None Detected
VFT – 12"x12" Beige with Thin Brown Streaks	Labs, Offices, Lounge, ECG Department and File Storage.	5000 SF	00027A	VFT - Chrysotile Mastic – None Detected
CT - 24"x48" Lay-in Pinhole and Texture Pattern	Basement ECG Department (Mixed with Non ACM Ceiling Tiles)	50 SF	0030A	Amosite
Transite Board	Basement Corridor Former Vestibule Entrance, North End of the Basement Main Corridor, Lounge and Lab #2	60 SF	N/A	Presumed ACM

	Ground Floor			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
VFT – 12"x12" Yellow with White Streaks	Ground Floor ER Waiting Room	N/A	0007A	VFT - Chrysotile Mastic – None Detected
VFT – 12"x12" Beige with Thin Brown Streaks	Palliative Care Department, Break Room and Patient Rooms in the ER Department, EMS Room Closet.	2000 SF	00027A	VFT - Chrysotile Mastic – None Detected
Transite Board	Exterior Entrance to ER Department	500 SF	N/A	Presumed ACM



Main Hospital - Kitchen Area (1986)

	Ground Floor			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Transite Pipe (Rain Water Leaders)	Service Corridor	6 LF	N/A	Presumed ACM
	Kitchen, Office, and Dish Room	100 LF		
	Ingredients Storage Room	20 LF		
	Dry Good Storage	20 LF		
	Cafeteria	40 LF		
	Ladies' Locker Room and Washroom Area	25 LF		
	Halfway Café Lounge	15 LF		
	Men's Locker Room and Washroom Area	30 LF		

Alexander Globe Centre - Former Nurses' Residence (1948)

	Attic Level			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Aircell	Attic (Visible above Hatches within Washroom and Mechanical Room)	80 LF	N/A	Chrysotile

	Ground Floor			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
VFT – 9"x9" Beige with Red Streaks	Janitor's Closet, Stationery Closet, and Sprinkler Room	80 SF	0060A-C	VFT - Chrysotile
				Mastic – Chrysotile
VFT – 12"x12" Beige with Orange Flecks	Vestibule, Washroom in PC Room #1, and Front Entrance	350 SF	0061A-C	VFT – None Detected
				Mastic – Chrysotile



	Exterior			
Material	Locations	Approx. Quantity	Sample Number(s)	Result (if ACM)
Transite Panels	Exterior Siding	5000 SF	N/A	Presumed ACM